

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,353,438 B2
APPLICATION NO. : 10/645861
DATED : April 1, 2008
INVENTOR(S) : Wingyu Leung et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title Page, FOREIGN PATENT DOCUMENTS, add -- GB 2289779 11/1995 --.

Drawings:

Delete drawing sheet 11 of 11 and substitute therefor the attached Drawing Sheet containing Fig. 11.

Column 1, line 30, amend "Semiconductors" to -- Semiconductor --.

Column 4, line 6, amend "stuck at" to -- stuck-at --.

Column 4, line 28, amend "stuck at" to -- stuck-at --.

Column 9, line 66, replace "1" with a comma.

Column 10, lines 27-28, delete "The logic high RESET signal also sets the read pointer value RP provided by toggle flip-flop 313 to a logic."

Column 12, line 66, insert -- 102 -- after "sequencer".

Column 13, line 11, amend "doe" to -- does --.

Column 13, line 38, insert -- to -- before "have".


Column 13, line 66, delete "the" (first occurrence).

Column 17, line 33, amend "I11" to -- 111 --.

Column 22, line 54, amend "So" to -- S0 --.

Signed and Sealed this

Second Day of December, 2008



JON W. DUDAS
Director of the United States Patent and Trademark Office

U.S. Patent

Apr. 1, 2008

Sheet 11 of 11

7,353,438 B2




FIG. 11